



HOWARD COUNTY, MARYLAND

OFFICE OF PURCHASING

6751 Columbia Gateway Drive, Suite 501, Columbia, MD 21046

**ADDENDUM NO. 1
ISSUED NOVEMBER 4, 2016
INVITATION FOR BIDS**

**IFB NO. 2017-28
VIDEO INSPECTION OF SANITARY SEWER MAINS**

OPENING: NOVEMBER 16, 2016 AT 11:00 A.M.

<https://www.howardcountymd.gov/Departments/County-Administration/Purchasing>

This addendum is hereby made a part of this IFB No. 2017-28. Note the following information and submit the bid accordingly.

Clarifications/Changes

Refer to IFB Page 15, Section D 12.7. **Delete** this section in its entirety and **replace** with the following:

12.7 The Contractor shall be required to remove any plywood channel protectors (or place them on the bench and out of the way for inspection) or other visible debris that would obstruct the performance of the televised inspection from the manholes prior to inspection. When the Contractor has finished televising a particular line segment that contains channel covers, the Contractor shall replace them over the channels to protect the sewer from falling debris. If there is debris in the main, it is the responsibility of the developer to clean and re-inspect the main.

All other specifications, terms and conditions remain the same.

Please acknowledge addenda by signing below and returning with the bid. Failure to acknowledge this addendum may be cause for rejection of the bid.

ADDENDUM RECEIVED BY:

Company Name	Signature
	Title

IBC