

11-ft from center of edge line to center of roadway

Repaint existing double yellow lines

Example of 5 inch white edge line along Dorchester Way



Example of Speed Hump



Speed Hump near 10825 Dorchester Way






Example of a Raised Intersection




Raised Intersection at Hounslow Dr and Dorchester Way



Repaint existing double yellow lines

Example of 5 inch white edge line along Dorchester Way

Potential Bike lane

Dorchester Way Traffic Calming	
Proposed Speed Humps, proposed raised intersections, proposed edge lines, double yellow line (repaint), and Speed Feedback Signs	
	June 2025




Crosswalk exist at Folkestone Way/Birmingham Way and Dorchester Way refresh crosswalk



Speed Hump exist upgrade to Raised Intersection at Sandown Way/ Petersboro Rd and Dorchester Way



Speed Hump 200ft north Chester Way on Dorchester Way



11-ft from center of edge line to center of roadway

Repaint existing double yellow lines

Example of 5 inch white edge line along Dorchester Way

Dorchester Way Traffic Calming	
Proposed Speed Humps, proposed raised intersections, proposed edge lines, double yellow line (repaint), and Speed Feedback Signs	
	June 2025

Bike lanes are not considered a traffic calming device. For general information regarding bike lanes and Bike Howard projects under the purview of the Howard County Office of Transportation, please call (410) 313-4312.

